

Functional Safety Assessment of Train Order Working


Kevin Anderson

Kevin J Anderson & Associates Pty Ltd

Melbourne Australia



Railways of Australia: Multitude of safeworking and communications systems - single line territory - long distance, low density, locomotives



Broken Hill

Ivanhoe

Parkes

Orange

Traditional staff and ticket safeworking with copper wire signal telephones necessitated constant stopping.

Communications replaced by Train Radio System (TRS) including trackKm to nearest 0.5 km from Global Positioning System (GPS).

Tender of Train Order Working (TOW) 1994. Risk assessment:

'not less safe' requires computer support to Train Controller (TC)



Trial implementation: Orange - Parkes and Orange - Dubbo 1998

Train Controller (TC) formulates authority (Train Order for train, Track Warrant for trackforce), details are read out and written down including security code. Handed back verbally on fulfillment and train clear of territory or protected by another authority.

Legacy System

Alternative Safeworking System

ASW was implemented in Victoria in 1993 and provided for transmission of train orders one section at a time to in-cab screens displaying 'Current' and 'Next' Orders.

The following screen shows a functional safety audit time-distance graph. In the centre, train 9823 is going down and train 9712 is travelling up and waits in the loop for 9823 to cross.

Functional Safety Assessment Audit Tool

An audit tool was developed to read radio and system logs and reconstruct the 'life cycle' of an authority from the 27 types of messages.

Typically, an authority goes through five steps to establish (proposed, validated, sent to train screen, acknowledged by train driver, acknowledged by system) and three steps to clear (relinquished by TD, returned and released).

errorWatch

more traps

a traps

ind file sizes

2219235

update_sync

1455422

logon_cb

auth_propose

auth_valid

auth_invalid

auth_checked

auth_reject

1200_authority_te

auth_return_reject

1200_cdc_ack

auth_td_ack

taq_update_sync

1200_cur_auth_c

VO.7 Handlers

ok_cb Mishap Crea

track_assign

w_msl_initiate

w_msl_remove

icu_ok_cb

taq_icu_depart

auth_location_rep

auth_return

auth_accept_return

auth_return(train)

logoff_cb

Work Gang Create

Work Gang Release

Road Rail Occupat

Road Rail Release

set event log

setAll

set start

EventLog 892909 chars 892909

set restart

errorFile

[9aa1] Fri Oct 17 09:01:36 1997 >>>auth_w_propose.c:auth_w_propose_resume SHUNT Auth Propose ok:(ELECTRONIC Auth_id=26270,"1111_18OCT 26270 MDA->YEL->MDA SHUNT", TC=S.J.SURMIAK,TAQ-Index=Pos=-1 ST=MDA_S8A ET=MDA_S8 OT=MDA_S9A).

set radio log

George HD:Clients:Victrack:Data from Victrak 31/10:RADIO.RM3

set start

621982 chars 621982

set track monitor

George HD:Clients:Data from Victrak 31/10:TRACK.RM3

set start

trackMoni chars trackMoni Track Monitor time 00:11:

George HD:Clients:Victrack:Data from Victrak 31/10:EVENT.RM3

George HD:Clients:Victrack:Data from Victrak 31/10:RADIO.RM3

George HD:Clients:Data from Victrak 31/10:TRACK.RM3

George HD:Clients:Victrack:Data from Victrak 31/10:Plot 17 October 97"

ELECTRONIC Auth_id=26270, MDA->YEL->MDA SHUNT", TC=Index=Pos=-1 ST=MDA_S8A E S9A

auth info auth name

1111_18OCT 26270 MDA->YE

start en

start MDA en

start MDA_S8A en

shunt MDA_S9A

radio log delimiters clarabel. 980436

AuthorityID m

train ID 1111_18OCT 98

2-

16

2-

radio log time 09:01:34

start

end

radio train ID 9188

radio auth key TOL->SLL

[1fe5] <<<< Fri Oct 17 0

[2462]

[27a7] type = 1200_cdc_ack_va

[0143] channel = 0, pid = 2523,

009188, tci = 0.

[1bc5] Replying to : 38000003

WATCHEM,WCH

WATCHUPGA,WHA

WERNETH B.P.,WEZ

WERNETH BP,WEZ

WESTMERE,WSM

WINGEEL,WGI

WOOMELANG,WMG

YATPOOL BP,YPZ

Territory North Geelong to Maryborough

r2a.ID bkgnd button ID 6179 of bkgnd ID 103 of window ID 101 of project "George HD:Clients:Victrack:Data from Victrak 31/10:Plot 17 October 97"

Evidence

The audit tool creates a graphical representation of each authority bounded in space and time. The history of each authority state is stored in the script or tag of each graphic

As a matter of 'proof by result' the relevant original log files are also stored in the tag.

The audit tool allowed measurement of controller workload and human error rates as well as providing a basis for enhanced integrity testing of the safeworking interlocking rules.

Train Management Control System (TMCS)

Due to legacy system problems revealed by the FSA audit, TMCS was declared to be NOT safety-related. The promised use of dual programming had not been installed and inspection of the source code revealed more problems than answers.

Rather, it was decided to restore confidence in integrity of the interlocking through a safety-related GPS Watchdog.

GPS Watchdog

- Stage 1 as installed June 1999:
 - Proof of TMCS and GPSW intercommunications
 - TRS polling ability
 - Plotting of both systems on Map and Graph
- Stage 2
 - Proximity detection and alarm capabilities
- Stage 3
 - Diverse implementation of safeworking rules

Risk Assessment

1. Train Location sub-system (Train Driver and Train Controller and GPS Watchdog)
 - 4.4 chances per million per year.
2. Train Control sub-system (TC and TMCS and GPS Watchdog computer support)
 - 5.5 chances per million per year.
3. Communications sub-system (TD and TC and TRS).
 - 11.0 chances per million per year.
4. Train Driver sub-system (TD only)
 - 5.5 chances per million per year.

Reliability Block Diagram

Train Operations sub-system lifecycle	Train Location Error	Train Control Error	Communications Error	Train Driver Error
Credible Threat:	Misreport 1.00E-03	Rules Error 5.00E-04	Comms Failure 1.00E-04	Exceed Authority 1.00E-05
Moderated by Sensible Precaution:	Track Km 4.00E-04	Computer Interlock 1.00E-03	Local Fallback 1.00E-02	Overlap Recovery 5.00E-02
Loss of Control per exposure	4.00E-07	5.00E-07	1.00E-06	5.00E-07
times crossing trials per annum	110	110	110	110
times balance of probability of collision not avoided locally and fatality per collision	20% 50%	20% 50%	20% 50%	20% 50%
Individual risk contributor chances per million years	4.4	5.5	11.0	5.5
Total risk assessment:	26.4 chances of fatality per million years			

Human Error Probability

1 in 1000 ($1E-3$) is established in various studies dating back to Three Mile Island Inquiry, 1975 as a demand rate that complex systems should be designed to defend against. (e.g security code errors 6 in 20,000 is $3 E-4$).

TC claim $5E-4$ implies a second chance - propose then validate.

TD claim $1E-5$ assumes strong second chance equiv
SPAD caution AND stop

Failure Rate Assumptions

Track km check $1\text{E-}3$ without GPS, $4\text{E-}4$ with GPS.

Computer interlock $1\text{E-}3$ limit claim SIL2.

Enhanced test matrix $89 \times 74 = n = 7921$ test cases.

At 99% confidence $4.5/n = 5.84\text{E-}4$.

Overlap recovery (300m) less certain, say $5\text{E-}2$.

Safety Argument

- Exposure and balance of probability figures were used to translate relative risks to purported absolute figures, but the primary safety argument rests on the relative risks and the safety principles of 'not less safe', 'as low as reasonably practicable '(ALARP) and 'continuous improvement'.
- GPSW provides monitoring, alarms and enhanced safeworking rules. However, in-cab communications and enforcement remain for the future.


FSA Audit

An audit was conducted by the FSA after three years of operations. The audit comprised a document review and generative interviews at Orange Train Control Centre and with system maintainers.

A system snap shot was taken and safeworking encodings were reviewed.


Train Controller workload issues were raised, in particular the time consuming nature of voice transmissions.

Example of Rule Enforcement



As train 8888 is standing on main, 8885 cannot be issued order to loop until existing order to Yard Limit Board is fulfilled.

PKS-BKH plot



Location Types

In the GPS Watchdog, safeworking encoding tables have been prepared for nine types of location:


- STD Standard Crossing Loop
- SSB Standard Crossing Loop with Shunt Limit Boards
- BSB Block Location with Shunt Limit Boards (aka Siding)
- BLK Block
- PKW Parkes Sub siding no Up YLB
- ADJ Crossing Loop with Junction
- SIG Signalled Location
- SS Single Line Section
- MLS Mishap Line Section

Authority Cases


The encoding and exception tables cover numerous cases (refer overleaf for one example from matrix):

- Down Train Order (20 cases)
- Up Train Order (20 cases)
- Shunt Order (4 cases)
- Track Occupancy Down and Up (8 cases each)
- Mishap Down and Up (9 cases each)
- UNIMO (2), BIMO (2), BIMOL (2) B (1) L (2)

Train Order from Stuart Town to Wellington Yard Limit Board



Example of excessive polling due to portable logon issue



Next Steps

In-cab communication and location advice (the TC knows location of other trains, TD does not)

- Data transmission for efficiency as well as safety
- Future of Enforcement
- Tolerate risk vs timeline (continue to improve)
- Generic commercial-off-the-shelf (COTS) solution (applicable to track circuits (TX) not just Train Order Working (TOW))