





Analysis Topic: ***Runway Overrun at Sao Paulo-
Congonhas, 2007-07-17***
Analyst: ***Bernd Sieker***
Report created on: ***Thu Sep 06 16:15:00 CEST 2007***
Document version: ***Document version unknown***

INCIDENT ANALYSIS


Incident description:

An Airbus A320 operated by TAM Linhas Aereas overran the runway of CGH

Legend of Factorshapes



Why-Because Graph



Timeline of Events

Factor List - Overview

- 1 A/C overruns runway at approx. 100kts
- 2 A/C decelerates at 1.26m/s^2 instead of planned 3.0m/s^2
- 3 Low friction force from wheel brakes
- 4 Ground Spoilers do not deploy
- 5 Autobrake inoperational
- 6 TCU sends signal: thrust lever #2 at CL detent
- 7 Manual braking is delayed
- 8 Runway is wet
- 10 F/C did not expect ground spoilers not to deploy
- 11 F/C did not expect autobrake not to operate
- 12 F/C do not commence "LOSS OF BRAKING" procedure immediately
- 14 Runway LDA ~1880m and no RESA
- 15 Ground spoiler extension logic requires all thrust levers to be at or near idle or at reverse
- 16 A/THR systems maintains forward thrust on eng #2
- 17 A/THR system disconnects
- 18 Thrust on eng #2 freezes at approx EPR 1.18
- 19 A/THR system stays active in speed mode
- 20 Wheel brake application is delayed
- 21 Reverse thrust is selected on eng #1
- 22 A/C touches down at approx. 140 kts
- 23 F/C decide to use autobrake
- 24 Lower-than-expected aerodynamic drag
- 25 Lower-than-expected wheel brake deceleration
- 26 Persistent significant forward thrust
- 27 Significant lift from wings
- 28 Lowered friction coefficient
- 29 Low downforce on wheels
- 30 Low normal force
- 31 Runway surface is ungrooved
- 33 Design of A/THR control logic
- 34 Manual braking is not envisaged
- 35 Discrepancy between EPR values used by FADEC and by FMGC is larger than 0.15 for longer than 1.8s
- 36 Thrust lever angle sensors read thrust lever #2 at CL detent
- 37 EPR value becomes NCD
- 38 FADEC reduces EPR value used to ~0.75
- 39 Thrust reverser of engine #1 deploys
- 40 FMGC uses last valid EPR reading (~1.00, corresponding to IDLE thrust)
- 41 Hydroplaning
- 42 Thrust lever #2 remains at CL detent
- 43 Ground Spoilers extended annunciation does not appear

Factor List - Details

- 1 A/C overruns runway at approx. 100kts**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 2 A/C decelerates at 1.26m/s² instead of planned 3.0m/s²**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: Autobrake MED was selected, which sets a target deceleration of 3.0m/s²
- 3 Low friction force from wheel brakes**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 4 Ground Spoilers do not deploy**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 5 Autobrake inoperational**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 6 TCU sends signal: thrust lever #2 at CL detent**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 7 Manual braking is delayed**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 8 Runway is wet**
Type of Factor: State
Date/Time:
Actors involved:
Annotation: This autothrust disconnect mechanism is described in the Incident report of the Taipei-Sungshan-Overrun. It is assumed to be similar in this incident, pending confirmation from AI.
- 10 F/C did not expect ground spoilers not to deploy**
Type of Factor: Assumption
Date/Time:
Actors involved:
Annotation:
- 11 F/C did not expect autobrake not to operate**
Type of Factor: Assumption
Date/Time:
Actors involved:
Annotation:

- 12 F/C do not commence "LOSS OF BRAKING" procedure immediately**
Type of Factor: UnEvent
Date/Time:
Actors involved:
Annotation: "LOSS of BRAKING" is a so-called "memory item", and must be applied without delay, and without referring to paper.
- 14 Runway LDA ~1880m and no RESA**
Type of Factor: State
Date/Time:
Actors involved:
Annotation:
- 15 Ground spoiler extension logic requires all thrust levers to be at or near idle or at reverse**
Type of Factor: State
Date/Time:
Actors involved:
Annotation:
- 16 A/THR systems maintains forward thrust on eng #2**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation: Autothrust tries to maintain approach speed ("VAPP")
- 17 A/THR system disconnects**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 18 Thrust on eng #2 freezes at approx EPR 1.18**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 19 A/THR system stays active in speed mode**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: Since not both thrust levers were set to IDLE, autothrust remains active.
- 20 Wheel brake application is delayed**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 21 Reverse thrust is selected on eng #1**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 22 A/C touches down at approx. 140 kts**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:

- 23 F/C decide to use autobrake**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 24 Lower-than-expected aerodynamic drag**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation:
- 25 Lower-than-expected wheel brake deceleration**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation:
- 26 Persistent significant forward thrust**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation:
- 27 Significant lift from wings**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation:
- 28 Lowered friction coefficient**
Type of Factor: State
Date/Time:
Actors involved:
Annotation:
- 29 Low downforce on wheels**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation:
- 30 Low normal force**
Type of Factor: Process
Date/Time:
Actors involved:
Annotation:
- 31 Runway surface is ungrooved**
Type of Factor: State
Date/Time:
Actors involved:
Annotation:
- 33 Design of A/THR control logic**
Type of Factor: State
Date/Time:
Actors involved:
Annotation:
- 34 Manual braking is not envisaged**
Type of Factor: Assumption
Date/Time:
Actors involved:
Annotation:

- 35 Discrepancy between EPR values used by FADEC and by FMGC is larger than 0.15 for longer than 1.8s**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: This autothrust disconnect mechanism is described in the Incident report of the Taipei-Sungshan-Overrun. It is assumed to be similar in this incident, pending confirmation from AI.
- 36 Thrust lever angle sensors read thrust lever #2 at CL detent**
Type of Factor: Assumption
Date/Time:
Actors involved:
Annotation:
- 37 EPR value becoms NCD**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: NCD - "No Computed Data"

This autothrust disconnect mechanism is described in the Incident report of the Taipei-Sungshan-Overrun. It is assumed to be similar in this incident, pending confirmation from AI.
- 38 FADEC reduces EPR value used to ~0.75**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: This autothrust disconnect mechanism is described in the Incident report of the Taipei-Sungshan-Overrun. It is assumed to be similar in this incident, pending confirmation from AI.
- 39 Thrust reverser of engine #1 deploys**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation:
- 40 FMGC uses last valid EPR reading (~1.00, corresponding to IDLE thrust)**
Type of Factor: Event
Date/Time:
Actors involved:
Annotation: This autothrust disconnect mechanism is described in the Incident report of the Taipei-Sungshan-Overrun. It is assumed to be similar in this incident, pending confirmation from AI.
- 41 Hydroplaning**
Type of Factor: Assumption
Date/Time:
Actors involved:
Annotation:
- 42 Thrust lever #2 remains at CL detent**
Type of Factor: Assumption
Date/Time:
Actors involved:
Annotation:
- 43 Ground Spoilers extended annunciation does not appear**
Type of Factor: UnEvent
Date/Time:
Actors involved:
Annotation:

Actor List